





RESIDENTIAL INSPECTION

1234 Main Street Washington, KS 66968

> Buyer Name 09/05/2022 9:00AM



Inspector Christian Hanekom InterNACHI Certified home inspector 7857477806 hanekomcollc@gmail.com



Agent Name 555-555-5555 agent@spectora.com

TABLE OF CONTENTS

1: Inspection Details	9
2: Homesite	10
3: Roof	11
4: Exterior	22
5: Structure	26
6: Attic	28
7: Electrical	30
8: Garage	44
9: HVAC	49
10: Plumbing	57
11: Kitchen	63
12: Interior	65
Standard of Practice	69

THANK YOU! Thank you for choosing us to perform this General Home Inspection. We always endeavor to do our best to ensure that both the home and your investment in it are safe!

INSPECTION LIMITATIONS

The Inspection is Visual

The purpose of this report is to reflect as accurately as possible the visible condition of the home at the time of the inspection. Although the inspector may use basic instruments, the inspection performed to provide data for this report was primarily visual and non-invasive. This inspection is not a guarantee or warranty of any kind. Its purpose is to identify potential safety hazards and defects in home systems and their major, readily visible components.

SCOPE of the INSPECTION

The inspection was performed in compliance with the Standards of Practice of the International Association of Certified Home Inspectors. The following conditions lie beyond the scope of the General Home inspection:

- · Identification of building regulation violations;
- Conditions not readily observable;
- Failure to follow manufacturer's installation recommendations, or
- Any condition requiring research.

NOT TECHNICALLY EXHAUSTIVE

Please keep in mind that home inspectors are generalists, not specialists. Homes contain a huge variety of systems and components of different types, of varying quality and age, installed by those with varying skill levels in different climate zones.

To have the same level of expertise, library of knowledge, or to perform inspections to the same technical degree as would contractors specializing in each of those systems is not possible for a home inspector.

The General Home Inspection does not include confirmation of compliance with any manufacturer's recommended installation instructions, confirmation of property boundary limits, compliance with structure setback regulations, or other issues requiring special research.

Although some conditions commented on in this report may be building code violations, identification of building code violations lies beyond the scope of the

General Home Inspection. To understand more fully what is and is not included in a General Home Inspection, please visit the Standards of Practice page of the International Association of Certified Home Inspectors at https://www.nachi.org/sop.htm.

The goal of this inspection report is not to make a purchase recommendation, but to provide you with useful, accurate information that will be helpful in making an informed purchase decision.

Not Pass/fail

A property does not "Pass" or "Fail" a General Home inspection. An inspection is designed to reflect the visual condition of the home at the time of the inspection. Please feel free to contact me with any questions about either the report or the property, soon after reading the report, or at any time in the future!

READ the REPORT!

Please read your entire inspection report carefully. Although the report has a summary that lists the most important considerations, the body of the report also contains important information.

REPAIRS, EVALUATIONS, and CORRECTIONS

For your protection, and that of others, all repairs, corrections, or specialist evaluations should be performed by qualified contractors or licensed professionals. Safety hazards or poorly performed work can continue to be a problem, or even be made worse when home sellers try to save money by hiring inexpensive, unqualified workmen, or by doing work themselves. Be sure to take whatever actions are necessary before the expiration of your Inspection Object Deadline!

DO A FINAL WALKTHROUGH! Because conditions can change very quickly, we recommend that you or your representative perform a final walk-through inspection immediately before closing to check the condition of the property, using this report as a guide.

WE'RE HERE to HELP! If you have questions about either the contents of this report, or about the home, please don't hesitate to contact us for help, no matter how much time has passed since your home inspection. We'll be happy to answer your questions to the best of our ability.

NOTICE TO THIRD PARTIES This report is the joint property of the Inspection company that created it and the Client for whom it was prepared. Unauthorized transfer of this report to any third parties or subsequent buyers is not permitted and may place those in violation, or those who improperly depend on the information contained herein in jeopardy. This report and supporting inspection were performed according to a written agreement that limits its scope and the manner in which it may be used. Unauthorized recipients are advised to not rely on the contents of this report but instead to retain the services of the qualified home inspector of their choice to provide them with an updated report.

SUMMARY





CONCERN/MAINTENANCE NEEDED



MODERATE CONCERN/REPAIR



NEEDED

2.2.1 Homesite - Natural Hazards: Located near an agricultural area

- 3.1.1 Roof Roof Structure Ext. : Low spots
- 3.2.1 Roof Underlayment: Improper overlap: eve flashing
- 3.5.1 Roof Vents: Combustion vent: cap hail damage
- 🕞 3.5.2 Roof Vents: Flashing: penetration, improper- QC
- ⊖ 3.5.3 Roof Vents: Plumbing vent: height, too low- QC
- ⊖ 3.6.1 Roof Chimney: Cricket: none, > 30", OK
- ⊖ 3.6.2 Roof Chimney: Flashing: counter-flashing, bad install- QC
- 3.8.1 Roof Asphalt Shingles: Damage: workmen, minor
- O 3.8.2 Roof Asphalt Shingles: Fastening: fasteners visible
- 3.8.3 Roof Asphalt Shingles: Fastening: underdriven, protruding, a few
- 4.1.1 Exterior Grounds: Grading: negative grade- expansive soil
- 4.2.1 Exterior Driveway: Cracks: significant cracks > 1/4"
- 4.2.2 Exterior Driveway: Settling: moderate, compaction settling, complete
- ⊖ 4.3.1 Exterior Door/Window Exteriors: Doors: lintel corroded- QC
- ⊖ 4.3.2 Exterior Door/Window Exteriors: Doors: sealant needs maintenance- QC
- ⊖ 4.4.1 Exterior Wall Exteriors: Dryer exhaust duct: discharge cover, no damper- QC
- 4.4.2 Exterior Wall Exteriors: Weathering- commensurate with age
- 4.5.1 Exterior Exterior Trim: Exterior trim: installation poor
- A.5.2 Exterior Exterior Trim: Window trim: installation poor, all
- O 4.5.3 Exterior Exterior Trim: Window trim: sealant neeeded- QC
- ⊙ 5.2.1 Structure Floor Structure: Framing: floor framing damaged- QC
- 🕞 6.3.1 Attic Attic/Roof Structure Ventilation: Bathroom exhaust fan duct terminates in attic- QC
- 6.5.1 Attic Conventional Roof Framing: Debris in attic
- ⊖ 6.5.2 Attic Conventional Roof Framing: Roof framing: old practices typical
- ⊖ 6.9.1 Attic Attic Electrical, Plumbing and HVAC: Electrical: wires improperly terminated, off- QC

- 7.2.1 Electrical Service Panel: Interior: corrosion, minor- QC
- 7.2.2 Electrical Service Panel: Interior: dirty- QC
- 7.7.1 Electrical Main pannel: Amperage rating: 100 amps, marginal
- 7.7.2 Electrical Main pannel: Cable clamps missing QC
- 7.7.3 Electrical Main pannel: Inadequate working clearance
- ⊖ 7.7.4 Electrical Main pannel: Interior: corrosion- QC
- 7.7.5 Electrical Main pannel: Interior: paint overspray- QC
- 7.7.6 Electrical Main pannel: Numerous defects- QC
- ⊙ 7.7.7 Electrical Main pannel: OCPD: double-tapped breaker- QC
- 7.7.8 Electrical Main pannel: OCPD: GFCI, none installed
- 7.7.9 Electrical Main pannel: Wiring: multiple neutrals under one screw- Physicist
- 7.7.10 Electrical Main pannel: Wiring: wire termination improper- QC
- 7.8.1 Electrical Sub-Panel: Clamps/grommets/bushings missing- QC
- 7.8.2 Electrical Sub-Panel: Label: circuit directory, obsolete markings- QC
- 7.8.3 Electrical Sub-Panel: OCPD: breaker double-tap- QC
- 7.8.4 Electrical Sub-Panel: OCPD: no GFCI- install GFCI breakers
- 7.8.5 Electrical Sub-Panel: Wiring: damaged- QC
- 7.8.6 Electrical Sub-Panel: Wiring: termination improper QC

7.9.1 Electrical - Sub-Panel Grounding & Bonding: Equipment grounding: ground & neutrals terminate together- QC

- 7.10.1 Electrical Branch Circuits: AFCI: none installed (modern stds.)
- 7.10.2 Electrical Branch Circuits: Exterior receptacles: weather protected- No GFCI
- 🕞 7.10.3 Electrical Branch Circuits: GFCI: none installed- QC (long)
- 8.1.1 Garage Overhead Doors: Deterioration: severe- QC
- 8.1.2 Garage Overhead Doors: Door springs: no containment cable- QC
- 8.1.3 Garage Overhead Doors: Ends of useful lives- QC
- 🕒 8.1.4 Garage Overhead Doors: Paint peeling- QC
- ⊖ 8.1.5 Garage Overhead Doors: Sweep damaged/missing- QC
- 8.2.1 Garage Automatic Opener: Atomatic opener: older than 12 years
- 8.2.2 Garage Automatic Opener: Automatic opener: inoperable- QC
- 8.3.1 Garage Floors, Walls, & Ceiling: Ceiling fire barrier: holes in ceiling, adjoining living space- QC
- 8.4.1 Garage Conventional Doors: Door to exterior: binds at jamb: difficult to close- QC
- 8.5.1 Garage Garage Electrical: Freezer receptacle, non-GFCI
- ⊖ 9.1.1 HVAC Furnace & Humidifier : Backdrafting: corrosion- QC
- 9.1.2 HVAC Furnace & Humidifier : Clearance to combustibles: B-vent< 1" QC</p>
- 9.1.3 HVAC Furnace & Humidifier : Combustion chamber: burners, dirty, rusty-QC
- 🙆 9.1.4 HVAC Furnace & Humidifier : Combustion chamber: burners, flame color poor- QC
- ⊖ 9.1.5 HVAC Furnace & Humidifier : Combustion chamber: white powder, condensation- QC
- 9.1.6 HVAC Furnace & Humidifier : Condensation: corrosion inside furnace- QC
- 9.1.7 HVAC Furnace & Humidifier : Service recommended- QC

• 9.2.1 HVAC - Cooling: AC: old, functional, past design life

• 9.2.2 HVAC - Cooling: AC refrigerant Lines: damaged or missing insulation

10.3.1 Plumbing - Water Heater: Gas: combustion exhauGas water heater, vent inadequate clearance from combustibles- QC

- O 10.3.2 Plumbing Water Heater: Gas water heater: fuel supply, no drip leg- QC
- 10.3.3 Plumbing Water Heater: Past leakage, OK
- 10.3.4 Plumbing Water Heater: Water heater past design life
- 🕒 11.13.1 Kitchen Electrical: Receptacles: GFCI protection, none installed- QC
- 11.16.1 Kitchen Walls: Drywall, poor installation
- 12.2.1 Interior Floors: Wood floors: gaps, poor installation (loc)
- 12.4.1 Interior Ceilings: Damage/deterioration: minor
- O 12.12.1 Interior Interior Trim: Interior trim: missing- QC (loc)
- 12.13.1 Interior Bedroom: AFCI receptacles: none installed (BR)

1: INSPECTION DETAILS

1.1	Attendees
1.2	Animals onsite

Information

Attendees: AttendeesAttendees: Portion Attended byClientOccupantEntire

Weather, 2 days prior to the Inspection

Weather at the Inspection Sunny, Clear

Overcast with occasional light rain

Approximate Temperature at the Inspection 90s F, 80s F

Weather-related Property Condition Damp from recent rain

Utilities: all utilities on

All utilities were on at the time of the inspection.

Animals onsite: Dog: no problem

A dog was present at the property during the inspection, but was not a hindrance to the inspection.

2: HOMESITE

2.1	Inspection/Site Details
2.2	Natural Hazards

Information

Inspection/Site Details: Inspection/Site Details: Lot Slope

Approximate year of construction Moderate slope

1963

Limitations

Inspection/Site Details

DETACHED STRUCTURES NOT INSPECTED

The property included one or more detached structure (structures not attached to the home) which were not included as part of a General Home Inspection and were not inspected. The Inspector disclaims any responsibility for providing any information as to their condition. Consider having these structures inspected by a qualified inspector for safety reasons.

Inspection/Site Details

INSPECTED IN CONTEXT

Older home are inspected in the context of the time period during which they were built. Homes are not required to be updated to comply with newly enacted building codes and older homes typically reflect building practices that were locally common at the time they were built. Although the general home inspection does not include identification of building code violations, it is an inspection for system and major component deficiencies and safety issues regardless of home age.

Deficiencies

2.2.1 Natural Hazards

LOCATED NEAR AN AGRICULTURAL AREA

Minor Concern/Maintenance needed

The home was located near an active agricultural area. Some of the environmental concerns with this location are:

- Airborne particulates (dust) generated by farming methods;
- Airborne chemicals such as pesticides and fertilizers, especially when spray-applied. Low-level vapors from pesticides can sometimes be present for days or weeks after initial application.

Information about these hazards is widely available on the internet.

Recommendation Contact a qualified professional.

3: ROOF

3.1	Roof Structure Ext.
3.2	Underlayment
3.3	Roof Drainage System
3.4	Flashing
3.5	Vents
3.6	Chimney
3.7	ROOF REFERENCE
3.8	Asphalt Shingles

Information

Roof Configuration Gable and hip	Roof pitch, 4:12 The roof pitch (angle of slope) was approximately 4:12	Roof inspection method walked and viewed from ladder The inspector viewed the roof using this method.
Walked the roof The Inspector inspected the roof and its components by walking on the roof.	Underlayment: Type of Underlayment #15 black felt	Roof Drainage System: Drainage system materials seamless aluminum
Flashing : Flashing Material Aluminum	Chimney: Crown Material Concrete	Asphalt Shingles: Type of Fastening Roofing nails
Asphalt Shingles: Type of Shingle	Asphalt Shingles: Type of Valley	

3-Tab

Closed valley

Roof Structure Ext. : What's inspected?

Inspection of the roof structure from the exterior typically includes:

- The general roof structure appearance;
- Roof-covering material condition;
- Flashing protecting roof-covering material penetrations, changes in roof-covering materials, and transitions where roof slopes change;
- Condition of combustion, plumbing and attic ventilation vents and devices;
- Chimney conditions; and
- Roof drainage systems and components.

Roof Drainage System: Gutters & downspouts

The roof drainage system consisted of conventional gutters hung from the roof edges feeding downspouts.



West

North

Northeast



Roof Drainage System: What is inspected?

Inspection of the roof drainage system typically includes examination of any of the following:

- Gutters (condition and configuration);
- Downspouts & extensions (condition and configuration); •
- Scuppers; and •
- Overflow drains.

Flashing : General description

Flashing is a general term used to describe (typically) sheet metal fabricated into shapes and used to protect areas of the roof from moisture intrusion. Inspection typically includes inspection for condition and proper installation of flashing in the following locations:

- Roof penetrations such as vents;
- Electrical masts;
- Chimneys;
- Mechanical equipment;
- Patio cover attachment points;
- Around skylights;
- Junctions at which roofs meet walls;
- Roof edges;
- Areas at which roofs change slope;
- Areas at which roof-covering materials change; and
- Areas at which different roof planes meet (such as valleys).



Chimney: Crown: concrete

West

The chimney crown was constructed using concrete. Concrete is very durable and concrete crowns typically have a longer service life than the more common mortar crowns.



Chimney: Crown: OK

The Inspector observed no deficiencies in the condition of the chimney crown.


ROOF REFERENCE: Asphalt Shingle Reference

To follow the link, click it, and then click the icon on the left:

- Asphalt Shingle Inspection Checklist
- How to Check Bonding
- Craze-cracking
- Batch Problems
- Blisters VS Hail Damage
- Granule Loss
- Biological Growth
- Diagnosing Wind Damage
- Voiding the Manufacturer's Warranty
- Factors Affecting Shingle Aging
- Controlling Ice Dam Growth
- Shingle Performance Comparison
- Field Guide for Inspecting Asphalt Shingles, Kenton Shepard, \$14.99

Asphalt Shingles: Installation: racked OK

Asphalt shingles on this roof were installed with joints aligned vertically at alternate courses. This installation method is called racking. Although incorrect or not recommended for many types of shingles, this installation is correct for the types of shingles installed on this roof.



Asphalt Shingles: Substrate

1 layer




Asphalt Shingles: Substrate: 1 layer

The roof had one layer of asphalt shingles installed at the time of the inspection.

Asphalt Shingles: Valleys: conventional cut

The valleys were installed in a conventional manner with shingles from one slope overlapping the valley, and shingles on the adjoining slope cut in a line slightly offset from- and parallel to- the valley centerline.



Asphalt Shingles: Warranties: check with seller

Shingle condition indicated that the shingle warranty may not yet have expired. Confirmation would require documentation. Shingles may have one warranty, two warranties, three warranties, or no warranty at all. A warranty may transfer once with the sale of the home, or it may transfer as a limited warranty, or it may transfer fully. Time limits for notifying the shingle manufacture of the sale of teh home may exist. You should read the terms of any warranty carefully to determine whether any action is neccesary by you, or by the seller, for the warranty to remain in effect.

Limitations

Underlayment

DISCLAIMER: EDGES VISIBLE ONLY

The underlayment was hidden beneath the roof-covering material. The inspector was able to view edges only at representative areas around the perimeter of the roof. It was not inspected and the Inspector disclaims responsibility for evaluating its condition.

Chimney

FLUE: DISCLAIMER

Accurate inspection of the chimney flue lies beyond the scope of the General Home Inspection. Although the Inspector may make comments on the condition of the portion of the flue readily visible from the roof, a full, accurate evaluation of the flue condition would require the services of a specialist. Because the accumulation of flammable materials in the flue as a natural result of the wood-burning process is a potential fire hazard, the inspector recommends that before the expiration of your Inspection Objection Deadline you have the flue inspected by a specialist.

Chimney

FLUE: INACCESSIBLE, NOT INSPECTED- QC

The chimney flue was inaccessible without special equipment and was not inspected. Because the accumulation of flammable materials in the flue as a natural result of the wood-burning process is a potential fire hazard, the inspector recommends that before the expiration of your Inspection Objection Deadline you have the flue inspected by a specialist.

Asphalt Shingles

FASTENING: DISCLAIMER

The Inspector did not directly view the fasteners and disclaims responsibility for confirming proper fastening of the asphalt shingles. Fasteners used to asphalt connect asphalt shingles to the roof were not visible. At the time of the inspection the shingle sealant strips were fully bonded. Because a fully bonded roof is the most important factor in the wind resistance of the shingles, breaking shingle bonds to view fasteners would constitute damage to the roof. Destructive testing lies beyond the scope of the General Home Inspection. The Inspector observed no outward indication of fastener deficiencies.

Deficiencies

3.1.1 Roof Structure Ext.

LOW SPOTS

Minor Concern/Maintenance needed

Localized depressions (low areas) were visible in various areas of the roof exterior. This condition should not affect roof performance.

Recommendation

Contact a qualified roofing professional.



3.2.1 Underlayment IMPROPER OVERLAP: EVE FLASHING

Minor Concern/Maintenance needed

At the roof eves, roof edge flashing overlapped roof underlayment. This condition may result in decay of the lower edge of roof sheathing. Installation standards dictate that felt underlayment should overlap the edge flashing at eves.

Recommendation Recommend monitoring.

3.5.1 Vents

COMBUSTION VENT: CAP HAIL DAMAGE

Minor Concern/Maintenance needed

Caps of combustion exhaust vents on the roof exhibited denting typical of hail damage. This will not affect the ability of the vent caps perform as designed.



3.5.2 Vents

FLASHING: PENETRATION, IMPROPER- QC

Moderate Concern/Repair

One or more vent penetrations were incorrectly flashing at the time of the inspection. This condition increases the chance of roof leakage at these areas. The Inspector recommends correction by a qualified roofing contractor.

Recommendation Contact a qualified roofing professional.





PLUMBING VENT: HEIGHT, TOO

A plumbing vent pipe serving the drain, waste and vent system had inadequate clearance above the roof. To help ensure that they perform according to their design, plumbing vent pipes should

terminate a minimum of 6 inches above the roof or above the level of

anticipated snow accumulation. The Inspector recommends correction by a qualified plumbing contractor. Any necessary roof

repairs should be made by a qualified roofing contractor.

3.5.3 Vents

LOW-OC

3.6.1 Chimney

Recommendation

CRICKET: NONE, > 30", OK

Contact a qualified professional.

The chimney had no cricket. A cricket is a small roof built on the uphill side of the chimney to prevent roof drainage from pooling and causing damage from roof leakage. Crickets are recommended for chimneys measuring 30 inches or more in width (measured parallel to the eves). This chimney measured more than 30 inches in width. The Inspector observed no problems that appeared to be associated with this condition.

Moderate Concern/Repair

Recommendation Contact a qualified professional.

3.6.2 Chimney

FLASHING: COUNTER-FLASHING, BAD INSTALL- QC

Counter-flashing designed to work in conjunction with flashing where the chimney penetrated the roof was poorly installed. This condition may allow moisture intrusion with the potential to cause decay of the roof sheathing or framing, microbial growth, or damage to other home materials. The Inspector recommends correction by a qualified roofing contractor.

Recommendation

Hanekom Co. LLC

Contact a qualified roofing professional.









3.8.1 Asphalt Shingles

DAMAGE: WORKMEN, MINOR

Minor damage to the asphalt shingle roof appeared to be the result of careless workmen. It will not affect the ability of the shingles to perform as designed or affect their lifespan.



West

West

Northwest

Minor Concern/Maintenance needed

3.8.2 Asphalt Shingles

FASTENING: FASTENERS VISIBLE

Some asphalt shingles on the roof had fasteners visible. Exposed fasteners are considered by shingle manufacturers to be temporary repairs. This condition is typical of efforts to prevent wind damage to poorly-bonded shingles.

Recommendation Contact a qualified professional.



Southeast

3.8.3 Asphalt Shingles

Minor Concern/Maintenance needed

FASTENING: UNDERDRIVEN, PROTRUDING, A FEW

A few fasteners were protruding through the overlying shingles. This is typically caused when an installer uses a pneumatic nail gun with the air pressure adjusted too low. Damaged shingles should be replaced and the underlying shingles should be refastened.



4: EXTERIOR

4.1	Grounds
4.2	Driveway
4.3	Door/Window Exteriors
4.4	Wall Exteriors
4.5	Exterior Trim

Information

Driveway: Driveway Surface Concrete



Exterior Trim: Trim Material Same as siding

Wall Exteriors: Mostly OK

The Inspector observed few deficiencies in the condition of the exterior walls. Notable exceptions will be listed in this report.

Limitations

Door/Window Exteriors

UPPER LEVEL WINDOWS

The exterior of upper level windows could not be viewed as closely as windows at ground level.

Wall Exteriors

DISCLAIMER

Inspection of wall exteriors includes identification of deficiencies that are readily visible. The Inspector disclaims identification of deficiencies hidden from view inside the wall assembly.

Deficiencies

4.1.1 Grounds GRADING: NEGATIVE GRADE-EXPANSIVE SOIL

– Moderate Concern/Repair

The home had areas of neutral or negative drainage that will route runoff from precipitation toward the foundation. Because the home was in an area that may contain expansive soil, these areas should be re-graded to improve drainage near the foundation and help reduce the risk of foundation damage. The ground should slope away from the home a minimum of ¼-inch per foot for a distance of at least six feet from the foundation.

Recommendation

Contact a qualified fencing contractor



4.2.1 Driveway

CRACKS: SIGNIFICANT CRACKS > 1/4"

Significant cracks in the driveway should be filled with an appropriate material to avoid continued damage to the driveway surface from freezing moisture.

4.2.2 Driveway

SETTLING: MODERATE, COMPACTION SETTLING, COMPLETE

- Moderate Concern/Repair

Moderate settling of soil beneath the driveway has created a trip hazard.

4.3.1 Door/Window Exteriors

DOORS: LINTEL CORRODED- QC

The lintel above an exterior door was visibly corroded. This condition may damage the brick and will eventually structurally weaken the lintel. You should consult with a qualified contractor to gain an idea of options and costs for repair or replacement of any affected lintels. All work should be performed by a qualified contractor.

Recommendation

Contact a qualified masonry professional.







4.3.2 Door/Window Exteriors

DOORS: SEALANT NEEDS MAINTENANCE- QC

Sealant around door exteriors was old, discolored, cracked, and needed maintenance to avoid potential moisture intrusion. Work should be performed by a qualified contractor.

Recommendation

Contact a qualified professional.

4.4.1 Wall Exteriors

Moderate Concern/Repair **DRYER EXHAUST DUCT: DISCHARGE COVER, NO DAMPER-QC**

The dryer exhaust duct was not equipped with a backdraft damper. This condition may allow pests to enter the vent, where they may create obstructions with nesting materials, a potential fire hazard. A proper backdraft damper should be installed by a qualified contractor.

Recommendation Contact a qualified professional.

4.4.2 Wall Exteriors

WEATHERING- COMMENSURATE WITH AGE

The exterior walls exhibited weathering, wear, and deterioration commensurate with the age of the home.

4.5.1 Exterior Trim

EXTERIOR TRIM: INSTALLATION POOR

Exterior trim was generally poorly installed.

4.5.2 Exterior Trim

WINDOW TRIM: INSTALLATION POOR, ALL

Window trim was generally poorly installed.





Minor Concern/Maintenance needed

Minor Concern/Maintenance needed



4.5.3 Exterior Trim

WINDOW TRIM: SEALANT NEEEDED- QC

Window trim had gaps that should be filled with an appropriate sealant by a qualified contractor to help prevent moisture and insect entry.

Recommendation

Contact a qualified professional.







5: STRUCTURE

5.1	Foundation
5.2	Floor Structure
5.3	Slab-on-Grade

Information

Foundation: Foundation Configuration Basement, Crawlspace	Foundation: Foundation Wall Material Concrete, Concrete masonry unit (CMU)	Floor Structure: Floor Sheathing Plywood
Floor Structure: Floor Structure Support Beams Steel I-beam, Wood beam	Floor Structure: Intermediate Support Concrete masonry unit (CMU) piers	Floor Structure: Joist Material Conventional wood joists
Floor Structure: Perimeter Bearing Top of foundation wall	Floor Structure: Thermal Insulation fibverglass batt	

Limitations

Foundation CONCRETE FOUND. WALLS: HIDDEN, INSULATION

Most of the poured concrete foundation walls were hidden from view. Their inspection was limited to visible areas only.

Foundation **FOOTING: NOT VISIBLE** The footings were not visible.

Floor Structure
GENERAL CONDITION

Deficiencies

5.2.1 Floor Structure

FRAMING: FLOOR FRAMING DAMAGED- QC

Moderate Concern/Repair

Damaged framing visible in the utility room should be repaired by a qualified contractor.

Recommendation Contact a qualified carpenter.

6: ATTIC

6.1	Attic Access
6.2	Attic Conditions
6.3	Attic/Roof Structure Ventilation
6.4	Thermal Insulation
6.5	Conventional Roof Framing
6.6	Roof Trusses
6.7	Sheathing
6.8	Roof fasteners & Hardware
6.9	Attic Electrical, Plumbing and HVAC
6.10	Radiant Barrier

Information

Attic Access: Access Hatch Location Master bedroom closet, Halway bathroom closet	Attic Access: Attic access: direct entry The Inspector evaluated the attic by entering the attic space.	Attic/Roof Structure Ventilation: Attic Ventilation Method Soffit vents, Roof vents
Attic/Roof Structure Ventilation:	Attic/Roof Structure Ventilation:	Thermal Insulation: Application
Roof Structure Ventilation	Whole-house Fan Location	Type
Roof vents	Main floor hallway	Attic inside the thermal envelope
Thermal Insulation: Insulation	Thermal Insulation: Thermal	Conventional Roof Framing: Roof
Average Depth	Insulation Type	Framing Method
11-16 inches	Fiberglass batt	Conventional framing
Sheathing: Roof Sheathing Material 3/4-inch plywood		

Limitations

Attic/Roof Structure Ventilation

VENTILATION DISCLAIMER, YEAR-ROUND CONDITIONS

The Inspector disclaims confirmation of adequate attic ventilation year-round performance, but will comment on the apparent adequacy of the system as experienced by the inspector on the day of the inspection. Attic ventilation is not an exact science and a standard ventilation approach that works well in one type of climate zone may not work well in another. The performance of a standard attic ventilation design system can vary even with different homesite locations and conditions or weather conditions within a single climate zone.

Deficiencies

BATHROOM EXHAUST FAN DUCT TERMINATES IN ATTIC- QC

Exhaust fan ducts from one or more bathrooms discharge into the attic space. Any such fan should discharge to the home exterior because the high moisture content of discharge air may cause the development of microbial growth like mold. This duct should be extended by a qualified contractor to discharge bathroom air to the home exterior.

Recommendation Contact a qualified professional.

6.5.1 Conventional Roof Framing **DEBRIS IN ATTIC** Debris visible in the attic should be removed.

6.5.2 Conventional Roof Framing

ROOF FRAMING: OLD PRACTICES TYPICAL

Methods and materials used in the roof framing, while not acceptable by modern standards, were typical of methods and materials commonly used when the home was originally constructed.

Recommendation

Contact a qualified professional.

6.9.1 Attic Electrical, Plumbing and HVAC

ELECTRICAL: WIRES IMPROPERLY TERMINATED, OFF-QC

Improperly terminated electrical wires were visible in the attic. Wires should terminate in an approved junction box with a listed cover plate installed. Although they were not energized at the time of the inspection, if they are controlled by a switch, they may have the potential to become energized, which would be a shock/electrocution hazard or potential fire danger. These wires should be examined and terminated correctly by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.





Moderate Concern/Repair





7: ELECTRICAL

7.1	General Condition
7.2	Service Panel
7.3	Electric Meter
7.4	Service Drop
7.5	Service Entrance Cables
7.6	Service Grounding & Bonding
7.7	Main pannel
7.8	Sub-Panel
7.9	Sub-Panel Grounding & Bonding
7.10	Branch Circuits

Information

Service Panel: Main Disconnect Туре Fuse block

Service Panel: Main Disconnect Ampacity 100 amps



Service Panel: Overcurrent Protection Type Fuses- ferrule type

Service Panel: Service Panel Ampacity Could not be determined

Service Panel: Service Panel Location Home exterior rear

Service Panel: Service Panel Brand Service Panel: Service Panel Could not be determined Exposure Rating

Service Panel: Service Panel Type Electric Meter: Electric Meter Surface mount

Could not be determined

Location North Rear

Electric Meter: Electric Meter Type Service Drop: Service Conductors Service Drop: Service Type

3-wire (240V)

Meter main



North

Service Entrance Cables: Service Entrance Cable Ampacity 4/0 aluminum/200 amps

Main pannel: Main Disconnect Type 1st Floor Breaker Service Entrance Cables: Viewed Service Entrance Conductors at: In the service panel, At the weatherhead

Main pannel: Main Disconnect Ampacity 100 amps Service Grounding & Bonding: Grounding Electrode Type Water pipe

Overhead, Public utility

Main pannel: Overcurrent Protection Type Circuit breakers



Main pannel: Service Panel Ampacity



Main pannel: Service Panel Location Main floor

Sub-Panel: Disconnect Ampacity 100 amps

Main pannel: Service Panel Brand Main pannel: Service Panel Square D



Main pannel: Service Panel Type Flush mount

Sub-Panel: Disconnect type: breaker

The main disconnect for this sub-panel was a breaker type.



Sub-Panel: Label: sub-panel brand,

This sub-panel brand was Squire D.

Sub-Panel: Sub-panel Ampacity 100 amps

Exposure Rating

1

Sub-Panel: Amperage rating: mfgr's label, ____

The manufacturer's label listed the sub-panel rating as 100 amps.

Sub-Panel: Feeders: overhead Feeder conductors supply this

sub-panel were routed overhead.



Sub-Panel: Sub-panel Brand Square D

Sub-Panel: Sub-panel Type

Surface mount

Sub-Panel: Sub-panel Exposure	Sub-Panel: Sub-panel Location
Rating	Basement
1	
Branch Circuits: Branch Circuit	Branch Circuits: Overcurrent
Conductor Type	Protection Type

Non-metallic sheathed

ent **Protection Type** Circuit breakers

Electric Meter: Location: Back yard North

The electric meter was located in the back yard against the transmission pole.

Service Drop: Type of Attachment

Electrical mast



Service Grounding & Bonding: Ground & neutrals terminate same bus bar, OK

Ground and neutral wires in the service panel terminated on the same bus bar. This is not a concern.

Branch Circuits: About AFCI protection

An arc Fault Circuit Interrupter (AFCI) is a life-safety device (typically an AFCI circuit breaker or electrical outlet) designed to prevent fires by detecting unintended electrical arcs and disconnecting power to the affected branch circuit before the arc starts a fire.

AFCI protection of bedroom receptacles (including light fixtures and smoke alarms) was first required by the National Electric Code (NEC) in 1999 (USA) and 2002 (Canada).

AFCI devices and AFCI protection requirements have changed over the years and requirements vary by jurisdiction, depending on which set of standards has been adopted.

Limitations

Service Panel

AMPERAGE RATING: UNABLE TO DETERMINE

The Inspector was unable to determine amperage rating of the service panel due to missing or illegible label information.

Service Panel

LABEL: MANUFACTURER'S LABEL, ILLEGIBLE LABEL

The manufacturer's label for the service panel was illegible. The Inspector was unable to confirm the existence of proper conditions when confirmation would require information taken from this illegible label.

Service Panel

MANUFACTURER: UNABLE TO DETERMINE

The Inspector was unable to determine the service panel manufacturer due to missing information.



Service Entrance Cables

SEC MARKINGS NOT VISIBLE

Markings describing the amperage rating of the service entrance conductors were not visible on the conductor insulation and the Inspector was unable to confirm proper rating. Confirmation of correct service entrance conductor rating would require the services of a qualified electrical contractor.

Service Grounding & Bonding

ELECTRODE DISCLAIMER

The Inspector disclaims responsibility for positive identification of the service grounding electrode, its proper installation, and adequate performance for the following reasons:

- 1. The electrode is often hidden from view;
- 2. Electrode performance can vary with installation practice and soil conditions,
- 3. Measuring electrode performance requires specialized instruments and skills that lie beyond the scope of the General Home Inspection.

For an accurate evaluation of the electrical grounding electrode system you would need to hire a qualified electrical contractor.

Feeder conductors were not marked. or the markings were illegible. The Inspector was unable to determine the amperage rating of the feeder conductors supplying power to this sub-panel.

Branch Circuits

BRANCH CIRCUIT DESCRIPTION

Home branch circuit wiring consists of wiring distributing electricity to devices such as switches, receptacles, and appliances. Most conductors are hidden behind floor, wall and ceiling coverings and cannot be evaluated by the inspector. The Inspector does not remove cover plates and inspection of branch wiring is limited to those components that are readily visible, and to evaluating for proper response to testing of switches and a representative number of electrical receptacles.

Branch Circuits

SWITCH OPERATION: DISCLAIMER

Switches are sometimes connected to fixtures that require specialized conditions, such as darkness or movement, to respond. Switches sometimes are connected to electrical receptacles (and sometimes only the top or bottom half of an receptacle). Because outlets are often inaccessible and because including the checking of both halves of every electrical outlet in the home exceeds the Standards of Practice and are not included in a typical General Home Inspection price structure, and functionality of all switches in the home may not be confirmed by the inspector.

Switches: disclaimer

Deficiencies

7.2.1 Service Panel


INTERIOR:



Interior components of the electrical service panel exhibited minor amounts of corrosion indicating moisture intrusion. Corrosion can degrade electrical contacts with the potential to cause problems related to component overheating. If it continues over time, this condition could become a potential fire hazard. The inspector observed no obvious points of moisture intrusion.



7.2.2 Service Panel **INTERIOR: DIRTY-QC**



The interior of the electrical service panel cabinet was dirty. This condition can deteriorate electrical connections, a potential fire hazard. The interior should be cleaned by a qualified electrical contractor.

Recommendation Contact a qualified electrical contractor.



7.7.1 Main pannel

AMPERAGE RATING: 100 AMPS, MARGINAL

The manufacturer's label listed the service panel amperage rating at 100 amps, which is considered marginal by modern standards. 100 amp services were typically installed before modern appliances were common in homes. Homes with 100 amp services that contain modern electrical appliances such as dishwashers, dryers, ranges, water heaters and air conditioners may have a higher risk excessive amounts of breaker tripping. You may wish to consult with a qualified electrical contractor to discuss the need for and to determine options and prices for upgrading the service panel.

Serious Concern/Action Needed

Recommendation

Contact a qualified electrical contractor.

7.7.2 Main pannel

CABLE CLAMPS MISSING QC

Non-metallic conductors had no clamps installed where they passed through knock-outs in the electrical service panel. This condition can result in damage to the conductor from contact with the sharp edges of the metal cabinet, or can result in conductors being pulled loose from connections inside the panel; a potential a shock/electrocution or fire hazard. Devices approved for this purpose should be installed by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.



Moderate Concern/Repair

7.7.3 Main pannel

INADEQUATE WORKING CLEARANCE

The electrical service panel cabinet had inadequate working clearance in front. Modern safety standards require a minimum open space 30 inches in width for a height of 6 feet-6 inches. Minimum clearance in front of the cabinet should be 3 feet. This condition should be corrected as necessary for safety reasons.

Recommendation Recommended DIY Project



7.7.4 Main pannel


INTERIOR: CORROSION- QC

The interior of the electrical service panel cabinet exhibited moderate amounts of corrosion indicating some moisture intrusion. Corrosion can degrade electrical contacts with the potential to cause problems related to component overheating. Maintenance should be performed by a qualified electrical contractor to ensure that electrical connections have not deteriorated.

Moderate Concern/Repair

Recommendation

Contact a qualified electrical contractor.



7.7.5 Main pannel INTERIOR: PAINT OVERSPRAY- QC



Buyer Name

The interior of the electrical service panel cabinet was contaminated with paint overspray. This condition can deteriorate electrical connections, a potential fire hazard. The interior should be cleaned by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.

7.7.6 Main pannel

NUMEROUS DEFECTS- QC

The electrical service panel had numerous defects. A full electrical system evaluation and any necessary work should be performed by a qualified electrical contractor.

Moderate Concern/Repair

Recommendation

Contact a qualified electrical contractor.

7.7.7 Main pannel

OCPD: DOUBLE-TAPPED BREAKER- QC

In the service panel, two wires were connected to a breaker designed for only one wire. This is known as a "double-tap" and is a defective condition that should be corrected by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.

7.7.8 Main pannel

OCPD: GFCI, NONE INSTALLED

No Ground Fault Circuit Interrupter (GFCI) protection provided in the home. Although it may not have been required at the time the home was built, For safety reasons, consider having GFCI protection installed by a qualified electrical contractor to protect appropriate electrical circuits.

Recommendation

Contact a qualified electrical contractor.









7.7.9 Main pannel WIRING: MULTIPLE

Serious Concern/Action Needed

NEUTRALS UNDER ONE SCREW- PHYSICIST

On the neutral bus bar of the service panel, two neutral conductors were installed under a single screw. The magnetic fields of each of the two conductors can amplify each other and create a space time vortex into which all known matter can potentially collapse. This condition should be corrected by a gualified physicist.

Recommendation

Contact a qualified professional.

7.7.10 Main pannel

WIRING: WIRE TERMINATION IMPROPER- QC

One or more wires in the service panel were improperly terminated. This condition may be a potential shock/electrocution, or a fire hazard and should be corrected by a gualified electrical contractor.

Recommendation

Contact a gualified electrical contractor.

7.8.1 Sub-Panel

CLAMPS/GROMMETS/BUSH INGS MISSING-QC

Serious Concern/Action Needed

Non-metallic conductors passed through knock-outs in this subpanel that had no protective device installed. Connectors designed to protect conductors where they pass through sheet metal include bushings, cable clamps, and grommets.. Without some protective device, the sharp edges of sheet metal may damage the conductors. This condition is a potential a shock/electrocution or fire hazard. The Inspector recommends that protective devices approved for this purpose be installed by a gualified electrical contractor.

Recommendation

Contact a gualified electrical contractor.











7.8.2 Sub-Panel

LABEL: CIRCUIT

Serious Concern/Action Needed

DIRECTORY, OBSOLETE MARKINGS- QC

Circuit names listed on the Circuit Directory of this sub-panel designed to identify individual branch circuits appeared to be old and may be inaccurate. Individual branch circuits should be accurately identified and clearly labeled so that they can be shut down quickly in an emergency.

Recommendation

Contact a qualified electrical contractor.




7.8.3 Sub-Panel

OCPD: BREAKER DOUBLE-TAP- QC

Serious Concern/Action Needed

In this sub-panel, two wires were connected to a breaker designed for only one wire. This is known as a "double-tap" and is a defective condition that should be corrected by a qualified electrical contractor. Recommendation

Contact a qualified electrical contractor.



7.8.4 Sub-Panel

OCPD: NO GFCI- INSTALL GFCI BREAKERS

– Moderate Concern/Repair

No Ground Fault Circuit Interrupter (GFCI) protection was provided to circuits controlled by this sub-panel. For safety reasons, consider having GFCI protection installed to meet modern requirements.

Serious Concern/Action Needed

Recommendation

Contact a qualified electrical contractor.


7.8.5 Sub-Panel

WIRING: DAMAGED-QC

Damaged wires visible in this load center should be repaired or replaced by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.



7.8.6 Sub-Panel

WIRING: TERMINATION IMPROPER - QC



Wires in this sub panel were improperly terminated. This condition should be corrected by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.

7.9.1 Sub-Panel Grounding & Bonding

EQUIPMENT GROUNDING: GROUND & NEUTRALS TERMINATE TOGETHER- QC

Grounding and neutral conductors in this sub-panel terminated on the same bus bar. In sub-panels, neutral conductors must be electrically isolated from the grounding system components. This condition is improper and should be corrected by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.



No arc fault circuit-interrupter (AFCI) protection was installed in the home. Although AFCI protection may not have been required when the home was originally constructed, to reduce the the danger of electricalsource fire, consider having AFCI protection installed that will comply with modern electrical safety standards.

Recommendation

Contact a qualified professional.

7.10.2 Branch Circuits

EXTERIOR RECEPTACLES: WEATHER PROTECTED- NO GFCI

Although electrical receptacles were enclosed in weatherproof enclosures, no Ground Fault Circuit Interrupter (GFCI) protection was provided them. Although GFCI protection of exterior circuits may not have been required at the time in which this home was built. Updating the existing exterior electrical circuits to include GFCI protection would improve electrical safety. This can be achieved by:

1. Replacing the current standard receptacles with GFCI receptacles.

2. Replacing the electrical circuit receptacles located closest to the main electrical service panel with a GFCI receptacles. 3. Replacing the breaker currently protecting the electrical circuit that supplies these receptacles with a GFCI breaker





Serious Concern/Action Needed





7.10.3 Branch Circuits

GFCI: NONE INSTALLED- QC (LONG)



No ground fault circuit interrupter (GFCI) protection of electrical receptacles was provided. Although GFCI protection may not have been required when this home was built, modern electrical safety standards require GFCI protection of receptacles at certain locations in the home. You should consult with a qualified electrical contractor to discuss options and costs for installation of GFCI protection.

This can be achieved relatively inexpensively by:

1. Replacing an individual standard receptacle with a GFCI receptacle (will protect that receptacle and all those downstream).

2. Replacing the electrical circuit receptacle located closest to the overcurrent protection device (usually a breaker in a panel) with a GFCI receptacle that will protect all those downstream. or

3. Replacing the breaker currently protecting the electrical circuit that contains the receptacles of concern with a GFCI breaker (will protect all receptacles on that circuit).

All work should be performed by a qualified electrical contractor.

Recommendation

Contact a qualified electrical contractor.

8: GARAGE

8.1	Overhead Doors
8.2	Automatic Opener
8.3	Floors, Walls, & Ceiling
8.4	Conventional Doors
8.5	Garage Electrical

Information

Garage Description

3-car

Automatic Opener: Number of Automatic Openers

2



Older garage

The garage was older and did not comply with modern safety regulations. Homes are not required to have systems updated to comply with newly enacted building codes.

Overhead Doors: Automatic opener: manual disconnect, OK

At the time of the inspection, the Inspector observed no deficiencies in the operation of the manual disconnect.

Overhead Doors: Overhead doors: what's inspected?

Inspection of overhead garage doors typically includes examination for presence, serviceable condition and proper operation of the following components: - door condition; - mounting brackets; - automatic opener; - automatic reverse; - photo sensor; - switch placement; - track & rollers; and - manual disconnect.

Limitations

Automatic Opener **AUTOMATIC REVERSE: DISCLAIMER**

Garage doors are not tested by the Inspector using specialized equipment and this inspection will not confirm compliance with manufacturer's specifications. This inspection is performed according to the Inspector's judgment from past experience. You should adjust your expectations accordingly. If you wish to ensure that the garage door automatic-reverse feature complies with the manufacturer's specifications, you should have it inspected by a qualified garage door contractor.

Deficiencies

8.1.1 Overhead Doors

DETERIORATION: SEVERE-QC

Moderate Concern/Repair

The overhead garage doors exhibited general severe deterioration. The Inspector recommends that before the expiration of your Inspection Objection Deadline you consult with a qualified contractor to discuss options and costs for maintenance or repair.

Recommendation

Contact a qualified garage door contractor.



Serious Concern/Action Needed

8.1.2 Overhead Doors

DOOR SPRINGS: NO CONTAINMENT CABLE- QC

Extension springs installed at a garage door did not have containment cables installed. Extension springs should have containment cables installed to help prevent potential serious or fatal injury if a spring should break. The Inspector recommends correction by a qualified contractor.

Recommendation

Contact a qualified professional.



8.1.3 Overhead Doors ENDS OF USEFUL LIVES- QC

Serious Concern/Action Needed

The garage vehicle doors were old, deteriorated and at or near the end of their useful lives. You should consult with a qualified contractor to discuss options and costs for replacement.

Recommendation

Contact a qualified garage door contractor.

8.1.4 Overhead Doors
PAINT PEELING- OC

One or more overhead garage doors had peeling paint. The Inspector recommends maintenance be performed by a qualified contractor.

Recommendation

Contact a qualified painting contractor.

8.1.5 Overhead Doors

SWEEP DAMAGED/MISSING-QC

The garage door sweep was damaged or missing. The sweep is the rubber gasket installed on the bottom of the door that seals the garage agains air movement and pest entry.

Recommendation

Contact a qualified garage door contractor.

8.2.1 Automatic Opener

ATOMATIC OPENER: OLDER THAN 12 YEARS

The garage door opener appeared to be older than 12 years and may need replacement soon.

8.2.2 Automatic Opener

AUTOMATIC OPENER: INOPERABLE- QC

An automatic door opener was inoperable. The Inspector recommends service by a qualified contractor or technician.

Recommendation

Contact a qualified garage door contractor.






Moderate Concern/Repair







Minor Concern/Maintenance needed



8.3.1 Floors, Walls, & Ceiling

Moderate Concern/Repair

CEILING FIRE BARRIER: HOLES IN CEILING, ADJOINING LIVING SPACE- QC

The garage ceiling had holes at the time of the inspection. These holes should be repaired to provide an intact fire-resistant barrier between the garage and the adjoining living space.

Recommendation

Contact a qualified drywall contractor.



8.4.1 Conventional Doors

DOOR TO EXTERIOR: BINDS AT JAMB: DIFFICULT TO CLOSE-QC

The conventional door between the garage and the exterior was binding on the jamb and was difficult to open and close. The Inspector recommends that the door hardware be adjusted by a qualified contractor. Recommendation

Contact a qualified carpenter.

8.5.1 Garage Electrical **FREEZER RECEPTACLE, NON-GFCI**



A non-Ground Fault Circuit Interrupter (GFCI)-protected electrical receptacle present in the garage is allowed and is provided for use with a freezer. This receptacle was not labeled at the time of the inspection. The Inspector recommends labeling this receptacle to help ensure that those using it do not assume that they are protected by a GFCI device.

9: HVAC

9.1	Furnace & Humidifier
9.2	Cooling
9.3	Fireplace
9.4	Gas-Fired Heaters

Information

Furnace &	Humidifier	:	Air	Filter
Location				

Furnace blower compartment

r	Furnace & Humidifier : Air filter
	Size

16x25

Furnace & Humidifier : Annual Fuel Utilization Efficiency (AFUE) Rating Medium (80%-83%)

Furnace & Humidifier : Data plate: photo

The photo shows the furnace data plate or manufacturer's label

Furnace & Humidifier : Date of manufacture

The date of furnace manufacture appeared to be February 1983.

Furnace & Humidifier : Duct Type Sheet metal



Furnace & Humidifier : Energy Source Natural gas

Furnace & Humidifier : Furnace Location Utility room Furnace & Humidifier : Furnace Brand Westinghouse

Furnace & Humidifier : Furnace Fu

The serial number of the furnace **photo** was N35814. The f

Furnace & Humidifier : Furnace Efficiency Rating Medium

Furnace & Humidifier : Furnace shut-offs: electrical shut-off photo

The furnace electrical shut-off is shown in the photo.



Furnace & Humidifier : Furnace shut-offs: gas and electrical photo

The furnace electrical and gas shut-offs are shown in the photo.

Furnace & Humidifier :

Humidifier Type Evaporative

Furnace & Humidifier : Type of **Air Filter** Pleated



Cooling: AC Brand Trane

Cooling: Condenser: data plate: serial number

The AC compressor serial number was J24293380.

Cooling: AC: old but functional

The air-conditioning system appeared to be old but functioning as designed.

Cooling: Condenser: disconnect at Cooling: Whole-house Fan sub-panel

The air-conditioner disconnect was located at a sub-panel.

Location

date of manufacture

Cooling: Condenser: data plate:

The AC compressor date of

manufacture was 06/1994

Main hallway



Fireplace: Fireplace Type Masonry

Furnace & Humidifier : Furnace type: what is inspected?

Inspection of gas-fired furnaces typically includes visual examination of the following:

- Cabinet exterior;
- Fuel supply and shut-off (not tested);
- Electrical shut-off;
- Adequate combustion air;
- Proper ignition;
- Burn chamber conditions (when visible);
- Combustion exhaust venting;
- Air filter and blower;
- Plenum and ducts;
- Response to the thermostat;
- Return air system; and
- Condensate drain components (where applicable).

Furnace & Humidifier : Humidifier installed

The home had a humidifier installed in ductwork at the furnace.



Cooling: AC: what's inspected?

Inspection of the air-conditioning system typically includes visual examination of the following: - compressor housing exterior and mounting condition; - refrigerant line condition; - proper disconnect (line of sight); - proper operation (outside temperature permitting); and - proper condensate discharge. The system should be serviced at the beginning of every cooling season.

Cooling: Condenser: data plate, photo

Information from the air-conditioner compressor unit data plate is shown in the photo.

		100
		and some
		190000
XL 1200 MFR 06/94		
MOD. NO. TTX036C100A1 VOLTS 200/230		
SERIAL NO. J24293380 PH 1 HZ 60		
MINIMUM CIRCUIT AMPACITY 23.0 AMPS		· · ·
OVERCURRENT PROTECTIVE DEVICE USA CANADA		1
RECOMMENDED, FUSE / BREAKER (HACR) 40 40		
MAX FUSE / BREAKER (HACR) 40 40	1	1000
HOFC-22 9 LBS. 08 02. OR 4.31 Kg(m)		
BAYFCCY 077A REQUIRED INDOORS FOR RATED PERFORMANCE		
THE TRANE COMPANY OUTDOOR USE TYLER, TX 75711-8010 MADE IN USA		
COMPR. MOT. 17.0 RLA 200/230 V 91 LRA		
O.D. MOT. 1.50 FLA 200/230 V 1/5 HP		1
M.E.A. NO. 56-92E		
DESIGN PSI - HIGH 300 LOW 300 F. ID. XD4		
i and		
A CARLES AND A CARLES		
han		
E I		-
1.4		
	-	100

Limitations

Furnace & Humidifier

HEAT EXCHANGER: DISCLAIMER & FLAME COLOR CHANGE- QC

The Inspector specifically disclaims responsibility for identifying any problems with furnace heat exchangers because proper evaluation requires invasive, technically exhaustive measures that exceed the scope of the General Home Inspection. A change in the burner flame visible when the blower of the furnace was activated indicated a possible cracked heat exchanger. The Inspector recommends service by a qualified HVAC technician.

Furnace & Humidifier

INSTALLATION, DISCLAIMER

Confirmation of compliance with furnace manufacturers installation recommendations requires research that exceeds the scope of the General Home Inspection. Although the Inspector will endeavor to identify potential problems common to many heating systems, a full, technically exhaustive evaluation would require the services of a qualified HVAC contractor.

Cooling

PERFORMANCE DISCLAIMER- MULTI-STORY

The General Home Inspection does not include confirming even temperature distribution throughout the home by the cooling system. In multiple-story homes a temperature gradient will often exist, with upper floors being warmer than lower floors. You should ask the seller about this condition, keeping in mind that individuals often have their own perceptions of what constitutes adequate performance of the cooling system.

Moderate Concern/Repair

Deficiencies

9.1.1 Furnace & Humidifier

BACKDRAFTING: CORROSION-QC

QC Corrosion on the top of the furnace near the draft hood indicated that the furnace may have been backdrafting. "Backdrafting" is a condition in which the invisible, odorless, tasteless, toxic products of combustion from the furnace gas burner fail to exhaust to the home

exterior, but are pulled from the combustion exhaust vent into the living space, typically by low air pressure created by appliances or systems operating exhaust fans. Excessive exposure to these products of combustion can result in injury or death. The Inspector recommends that an evaluation and any necessary corrections be performed by a gualified HVAC contractor.

Recommendation

Contact a qualified HVAC professional.



9.1.2 Furnace & Humidifier

CLEARANCE TO COMBUSTIBLES: B-VENT< 1" - QC

Serious Concern/Action Needed

Buyer Name

The B-vent serving as the furnace combustion exhaust vent had inadequate clearance from combustible materials. B-vent requires a minimum 1-inch clearance from combustible materials. This condition is a potential fire hazard. The Inspector recommends that this condition be corrected by a qualified contractor.

Recommendation

Contact a qualified HVAC professional.



9.1.3 Furnace & Humidifier COMBUSTION CHAMBER: BURNERS, DIRTY, RUSTY- QC

Serious Concern/Action Needed

Excessive amounts of dirt and rust flakes on the furnace burner assembly may affect the burner function. Poor burner function can cause carbon monoxide to rise to unhealthy levels in the living space. Carbon monoxide is a toxic, odorless, tasteless, invisible gas. Excessive exposure can be fatal. The Inspector recommends service by a qualified HVAC contractor.

Recommendation

Contact a qualified HVAC professional.

9.1.4 Furnace & Humidifier

Serious Concern/Action Needed

COMBUSTION CHAMBER: BURNERS, FLAME COLOR POOR- QC

Poor flame color indicated that the furnace burner assembly needed to be cleaned and adjusted. Poor burner function can cause carbon monoxide to rise to unhealthy levels in the living space. Carbon monoxide is a toxic, odorless, tasteless, invisible gas. Excessive exposure can be fatal. The Inspector recommends service by a qualified HVAC contractor.

Recommendation

Contact a qualified HVAC professional.



Moderate Concern/Repair **COMBUSTION CHAMBER:** WHITE POWDER, CONDENSATION-QC

White crystalline deposits visible in the furnace combustion chamber indicate that the furnace exhaust venting system may be experiencing problems with condensation. Moisture from condensation can cause premature failure of furnace components or the furnace itself. The Inspector recommends service by a qualified HVAC contractor.

Recommendation

Contact a qualified HVAC professional.

CONDENSATION: CORROSION INSIDE FURNACE- QC

9.1.6 Furnace & Humidifier

Corrosion below the combustion exhaust vent inside the furnace indicated the presence of excessive amounts of moisture, typically related to condensation formed by improper furnace exhaust vent conditions. This condition may result in premature failure of furnace components. The Inspector recommends that the furnace be serviced by a qualified HVAC contractor.

Recommendation

Contact a qualified HVAC professional.

9.1.7 Furnace & Humidifier

SERVICE RECOMMENDED-QC

The Inspector recommends that furnace cleaning, service and certification be performed by a qualified HVAC contractor.

Recommendation

Contact a gualified HVAC professional.

9.2.1 Cooling

AC: OLD, FUNCTIONAL, PAST DESIGN LIFE

The air-conditioning system appeared to be old, well past the mid-point of its design life but functional. A system at this point in its lifespan might need replacement at any time.







Buyer Name

Moderate Concern/Repair

Serious Concern/Action Needed

Recommendation Contact a qualified professional.

9.2.2 Cooling



Insulation on the air-conditioning suction (large, insulated) line was damaged or missing at areas and should be replaced by a qualified HVAC contractor.

Recommendation

Contact a qualified professional.





10: PLUMBING

10.1	Water Supply
10.2	Drain, Waste and Vent (DWV)
10.3	Water Heater

Information


Water Supply: Distribution Pipe **Bonding**

Hot & cold bonded

Water Supply: Water Source Public

Water Heater: Data plate: photo

The photo shows the data plate of this water heater.



Water Heater: Serial number

This water heater serial number was . 1211/011039

Water Supply: Distribution Pipe Material ³/₄-inch copper tubing

Drain, Waste and Vent (DWV) : Drain, Waste, & Vent Pipe Materials Polyvinyl Chloride (PVC), Cast iron

Water Heater: Date of manufacture The date of manufacture for this

water heater appeared to be 3/16/2012.

Water Supply: Water Service Pipe Material CPVC

Drain, Waste and Vent (DWV): Sewer System Public

Water Heater: Gas Water Heater Efficiency Medium

Water Heater: Water Heater Brand State Industries

Water Heater: Water heater location garage

Water Heater: Water Heater Tank Water Heater: Water Heater Type Capacity

50 gallons

Gas-fired

Water Heater: About: Conventional Storage Tank Water Heaters

Storage tanks water heaters are the most common type of water heater. They consist of an insulated tank in which water is heated and stored until needed. When a hot water valve is opening somewhere in the home, hot water is pulled from a pipe at the top of the water heater. To prevent overheating resulting in the development of excessive pressure in the tank (with the potential for high-energy explosion) a temperature/pressure relief (TPR) valve is installed that is designed to open if either exceeds a preset level. Natural-gas water heaters typically use less energy and cost less to run (by about half) than electric water heaters, although gas models cost more at the time of purchase.

Water Heater: Gas: photo, shut-off valve: gas

The photo shows the location of the shut-off valve for gas at the water heater.



Water Heater: Gas: photo, shut-off valve: water

The photo shows the locations of shut-off valve for water at the water heater.



Water Heater: Gas water heater info

This water heater was gas-fired. Gas water heaters heat water using a gas burner located in a chamber beneath the water tank. The gas control mechanism contains safety features designed to prevent gas from leaking into the living space if the burner should fail for some reason. Gas-fired water heaters must be properly installed so that the gas fuel is safely delivered to the water heater and so that the water heater safely exhausts the products of combustion to the home exterior. Gas-fired water heaters can be expected to last the length of the stated warranty and after its expiration may fail at any time.



Water Heater: TPR valve: present

The water heater was equipped with a temperature/pressure relief (TPR) valve that was not operated by the Inspector. Operating the TPR valve lies beyond the scope of the General Home Inspection. The Inspector recommends that the TPR be operated by the homeowner monthly as a maintenance measure.



Water Heater: Water heater, what's inspected?

Water heaters should be expected to last for the length of the warranty only, despite the fact that many operate adequately for years past the warranty date. Water heater lifespan is affected by the following: The lifespan of water heaters depends upon the following: - the quality of the water heater; - the chemical composition of the water; - the long-term water temperature settings; and - the quality and frequency of past and future maintenance Flushing the water heater tank once a year and replacing the anode every four years will help extend its lifespan. You should keep the water temperature set at a minimum of 120 degrees Fahrenheit to kill microbes and a maximum of 130 degrees to prevent scalding.

Limitations

Water Supply

MAIN WATER SHUT-OFF: UNABLE TO IDENTIFY, COMPLICATED SYSTEM

The inspector was unable to identify the main water supply shut-off due to unfamiliarity with the relatively complicated plumbing supply system. The Inspector recommends evaluation of the water distribution system and tagging of the main shut-off valve by a qualified plumbing contractor.

Drain, Waste and Vent (DWV)

MOST DWV NOT VISIBLE

Most drain, waste and vent pipes were not visible due to wall, ceiling and floor coverings.

Water Heater

GAS: BURN CHAMBER SEALED

The burn chamber of the water heater was sealed and the inspector was unable to evaluate its condition.

Water Heater

GAS: FUEL SUPPLY: GAS OFF- QC

Gas was off at the main shut-off and the water heater could not be tested. The inspector recommends that this water heater be inspected by a qualified plumbing contractor after gas service has been restored to the home.

Water Heater

TPR VALVE: VALVE INSTALLED

The water heater was equipped with a temperature/pressure relief (TPR) valve (not tested).

Deficiencies

10.3.1 Water Heater

GAS: COMBUSTION

Serious Concern/Action Needed

EXHAUGAS WATER HEATER, VENT INADEQUATE CLEARANCE FROM COMBUSTIBLES- QC

The combustion exhaust vent of this gas-fired water heater had inadequate clearance from combustibles. This type of exhaust flue requires 1-inch clearance from combustible materials. This condition is a potential fire hazard and should be corrected by a qualified contractor.

Recommendation

Contact a qualified professional.



10.3.2 Water Heater

GAS WATER HEATER: FUEL SUPPLY, NO DRIP LEG- QC

The gas supply pipe had no drip leg. A drip leg is generally recommended but not always required, depending on the local Authority Having Jurisdiction (AHJ). The purpose of a drip leg is to prevent particulates or moisture from condensation from entering and clogging the water heater gas valve, which can cause the water heater to shut down. You may wish to consult with local HVAC contractors concerning the advisability of installing a drip leg in the gas line.

Recommendation

Contact a qualified plumbing contractor.

Minor Concern/Maintenance needed

10.3.3 Water Heater

PAST LEAKAGE, OK

Stains on the floor beneath this water heater indicated tank leakage. The moisture meter showed no elevated levels of moisture present in the floor at the time of the inspection, indicating that the stains are from a water heater that has been replaced.

Hanekom Co. LLC

Page 61 of 69



10.3.4 Water Heater **WATER HEATER PAST DESIGN LIFE**



This water heater appeared to be past its design life and may need replacement soon.

11: KITCHEN

-	
11.1	General Condition
11.2	Cabinets
11.3	Countertops
11.4	Sink
11.5	Disposal
11.6	Dishwasher
11.7	Trash Compactor
11.8	Range
11.9	Oven
11.10	Range Hood
11.11	Cooktop
11.12	Microwave
11.13	Electrical
11.14	Lighting
11.15	Floors
11.16	Walls
11.17	Ceiling
11.18	Interior Trim
11.19	Refrigerator
11.20	Skylight

Information

Dishwasher: Dishwasher Brand	Range: Range/Cooktop Brand	Range: Range Hood Type
Maytag	Samsung	Re-circulating
Oven: Built-in Oven(s) Built-in electric	Cooktop: Range/Oven/Cooktop Type Electric range	Refrigerator: Refrigerator Brand: Samsung

Deficiencies

11.13.1 Electrical

RECEPTACLES: GFCI PROTECTION, NONE INSTALLED- QC

Moderate Concern/Repair

No ground fault circuit interrupter (GFCI) protection of electrical receptacles was provided in the kitchen. The Inspector recommends that electrical receptacles located within 6 feet of a plumbing fixture be provided with ground fault circuit interrupter (GFCI) protection in good working order to avoid potential electric shock or electrocution hazards. This can be achieved relatively inexpensively by: 1. Replacing an individual standard receptacle with a GFCI receptacle. 2. Replacing the electrical circuit receptacle located closest to the overcurrent protection device (usually a breaker) with a GFCI receptacle. 3. Replacing the breaker currently protecting the electrical circuit that contains the receptacles of concern with a GFCI breaker.

11.16.1 Walls

DRYWALL, POOR INSTALLATION

Drywall in the kitchen exhibited evidence of poor installation practices.





12: INTERIOR

12.1	General Interior
12.2	Floors
12.3	Walls
12.4	Ceilings
12.5	Ceiling Fan
12.6	Lighting
12.7	Exterior Doors
12.8	Sliding Glass Door
12.9	Interior Doors
12.10	Windows
12.11	Skylight
12.12	Interior Trim
12.13	Bedroom
12.14	Bathroom
12.15	Laundry Room
12.16	Emergency Escape and Rescue Openings
12.17	Interior Trim

Information

<section-header><section-header></section-header></section-header>	Walls: Thermal Insulation, Walls Fiberglass batt/ R19	Interior Doors: Interior Door Types Hollow core
Windows: Window Frame Material Wood	Windows: Window Glazing Type Shingle-pane	Windows: Window Style(s) Single hung
Bedroom: Bedroom Floor Materials Carpet	Bedroom: Fireplace Type None, Central heat	Bathroom: Bathroom Configuration 2 sinks in cabinet/toilet/shower
Bathroom: Bathroom Floor Materials Carpet, Laminate	Bathroom: Flooring Material Carpet, Vinyl	Bathroom: Number of Bathrooms 3 bathrooms

Bathroom: Room Ventilation Exhaust fan Bathroom: Toilet type(s) Conventional Laundry Room: Number of laundry rooms ____ The home had one laundry rooms.

Limitations

Bathroom

WATER SUPPLY SHUT-OFFS, NOT OPERATED

Water supply shut-off valves for the toilet and sink were not operated but were evaluated visually only.

Laundry Room

DRYER EXHAUST DUCT: VISUAL INSPECTION ONLY

A dryer exhaust duct connection was installed in the laundry room. Although the Inspector operated the dryer briefly, the duct was examined visually only. A visual examination will not detect the presence of lint accumulated inside the duct, which is a potential fire hazard. The Inspector recommends that you have the dryer exhaust duct cleaned at the time of purchase and annually in the future to help ensure that safe conditions exist. Lint accumulation can occur even in approved, properly installed ducts. All work should be performed by a qualified contractor.

Deficiencies

12.2.1 Floors

WOOD FLOORS: GAPS, POOR INSTALLATION (LOC)

Moderate Concern/Repair

The wood floor in the foyer, dining room and the hallway had gaps visible. This is usually due to shrinkage after installation and is a sign of poor installation.

Recommendation


Contact a qualified professional.





12.4.1 Ceilings DAMAGE/DETERIORATION: MINOR

The ceiling in the Galway exhibited minor damage. Cracking was visible on ceiling joints in 2 locations in the hallway.



12.12.1 Interior Trim

INTERIOR TRIM: MISSING- QC (LOC)


Interior trim was missing in the living room and dining room.

Recommendation

Contact a qualified professional.







12.13.1 Bedroom

AFCI RECEPTACLES: NONE INSTALLED (BR)

Moderate Concern/Repair

Electrical receptacles in this bedroom were not protected by an arc-fault circuit interrupter (AFCI) device. AFCI protection may not have been required when the home was originally constructed. You should consult with a qualified electrical contractor to discuss installation of AFCI protection to meet modern electrical safety standards.

Recommendation

Contact a qualified electrical contractor.

STANDARDS OF PRACTICE

Inspection Details

YOUR STANDARDS OF PRACTICE